



## Inspection Report

UNIVERSITY OF NORTH CAROLINA

Customer ID: **826**

Certificate: **55-R-0004**

@ CHAPEL HILL

Site: 001

1100 BIOINFORMATICS BLDG

DIVISION OF LABORATORY ANIMAL MEDICINE

Type: ROUTINE INSPECTION

Date: Jan-27-2010

CHAPEL HILL, NC 27599

### 3.2 (d)

#### INDOOR HOUSING FACILITIES.

Interior surfaces. The floors and walls of indoor housing facilities, and any other surfaces in contact with the animals, must be impervious to moisture. The ceilings of indoor housing facilities must be impervious to moisture or be replaceable.

\*\*\*In one cat room housing approximately a dozen cats, one area of the ceiling is water-damaged and the ceiling board has separated, creating a significant hole. The damaged area is not directly over the cat runs, however, ceilings in animal rooms need to be maintained so that they are impervious to moisture. Need to repair ceiling damage and underlying cause to ensure that the ceiling is impervious to moisture and can be adequately sanitized. Correct by February 28, 2010.

**Prepared By:**

F MIAVA BINKLEY, D V M      USDA, APHIS, Animal Care

**Date:**

**Title:** VETERINARY MEDICAL OFFICER Inspector 1020

Jan-28-2010

**Received By:**

(b)(6), (b)(7)(c)

**Date:**

**Title:**

Jan-28-2010



## Inspection Report

---

UNIVERSITY OF NORTH CAROLINA  
@ CHAPEL HILL  
1100 BIOINFORMATICS BLDG

Customer ID: **826**  
Certificate: **55-R-0004**  
Site: 001

DIVISION OF LABORATORY ANIMAL

Type: ROUTINE INSPECTION

Date: Jan-15-2009

CHAPEL HILL, NC 27599

---

### 2.33

#### ATTENDING VETERINARIAN AND ADEQUATE VETERINARY CARE.

Each research facility shall establish and maintain programs of adequate veterinary care.

\*\*\*At Hillsborough facility, several (6-10) dogs were observed with overgrown toenails. Need to trim nails more frequently to ensure adequate footing and comfort of animals. Correct by January 17, 2009.

---

**Prepared By:**

F MIAVA BINKLEY, D V M      USDA, APHIS, Animal Care

**Date:**

**Title:** VETERINARY MEDICAL OFFICER Inspector 1020

Mar-25-2009

**Received By:**

(b)(6), (b)(7)(c)

**Date:**

**Title:**

Mar-25-2009



## Inspection Report

UNIVERSITY OF NORTH CAROLINA

Customer ID: **826**

Certificate: **55-R-0004**

Site: 001

DIVISION OF LABORATORY ANIMAL MEDICINE

@ CHAPEL HILL

1100 BIOINFORMATICS BLDG

Type: ROUTINE INSPECTION

Date: Dec-04-2007

CHAPEL HILL, NC 27599

### 3.2 (d)

#### INDOOR HOUSING FACILITIES.

Interior surfaces. The floors and walls of indoor housing facilities, and any other surfaces in contact with the animals, must be impervious to moisture. The ceilings of indoor housing facilities must be impervious to moisture or be replaceable.

\*\*\*At Hillsborough facility, multiple walls have areas of blistering, peeling paint. This problem was identified by IACUC on last inspection and arrangements have been made with servicing company at this leased facility to repaint affected rooms. Complete correction by February 1, 2008.

**Prepared By:**

F MIAVA BINKLEY, D V M      USDA, APHIS, Animal Care

**Date:**

**Title:** VETERINARY MEDICAL OFFICER Inspector 1020

Dec-05-2007

**Received By:**

(b)(6), (b)(7)(c)

**Date:**

**Title:**

Dec-05-2007