



Inspection Report

LOS ANGELES BIOMEDICAL RESEARCH INSTITUTE

Customer ID: **1189**

Certificate: **93-R-0016**

L.A. BIOMED

Site: 001

1124 WEST CARSON STREET

LOS ANGELES BIOMEDICAL RESEARCH INSTITUTE

Type: ROUTINE INSPECTION

Date: May-07-2009

TORRANCE, CA 90502

No non compliant items identified this inspection.

Prepared By:

ALEXANDRA ANDRICOS, D.V.M. USDA, APHIS, Animal Care

Date:

Title: VETERINARY MEDICAL OFFICER Inspector 5038

May-08-2009

Received By:

(b)(6), (b)(7)(c)

Date:

Title:

May-08-2009



Inspection Report

LOS ANGELES BIOMEDICAL RESEARCH
L.A. BIOMED
1124 WEST CARSON STREET

Customer ID: **1189**
Certificate: **93-R-0016**
Site: 001

TORRANCE, CA 90502

LOS ANGELES BIOMEDICAL
Type: ROUTINE INSPECTION
Date: Apr-10-2008

3.125 (a)

FACILITIES, GENERAL.

(a) Structural strength. The facility must be constructed of such material and of such strength as appropriate for the animals involved. The indoor and outdoor housing facilities shall be structurally sound and shall be maintained in good repair to protect the animals from injury.

The ramp going into one of the pig enclosures has become detached from the cement it is usually attached to. While in use during the inspection, it slid and fell into the gutter that is below the ramp. Animals using the detached ramp may become injured. The outdoor housing facilities shall be structurally sound and shall be maintained in good repair to protect the animals from injury.

To be corrected by May 15, 2008

3.131 (c)

SANITATION.

(c) Housekeeping. Premises (buildings and grounds) shall be kept clean and in good repair in order to protect the animals from injury and to facilitate the prescribed husbandry practices set forth in this subpart. Accumulations of trash shall be placed in designated areas and cleared as necessary to protect the health of the animals.

***In the pig and sheep enclosures, the paint used to seal both the cement blocks (pig area) and wooden structures (sheep area) has rubbed off in several areas along the back walls. The underlying material is exposed and cleaning as required cannot be done. Also, directly behind the pig enclosures there is a broken door and a metal corrugated fence that has a large hole in it. An animal coming in contact with this area may become injured. Premises shall be kept clean and in good repair in order to protect the animals from injury and to facilitate the prescribed husbandry practices set forth in this subpart. Accumulations of trash shall be placed in designated areas and cleared as necessary to protect the health of the animals. ***

To be corrected by May 15th, 2008

Prepared By:

ALEXANDRA ANDRICOS, V.M.O USDA, APHIS, Animal Care

Date:

Title: VETERINARY MEDICAL OFFICER Inspector 5038

Apr-10-2008

Received By:

(b)(6), (b)(7)(c)

Date:

Title:

May-08-2008



Inspection Report

LOS ANGELES BIOMEDICAL RESEARCH
L.A. BIOMED
1124 WEST CARSON STREET

Customer ID: **1189**
Certificate: **93-R-0016**
Site: 001

LOS ANGELES BIOMEDICAL

Type: ROUTINE INSPECTION

Date: Apr-03-2007

TORRANCE, CA 90502

No non compliant items identified this inspection.

This is a recreation of inspection report:

1189 cust_id
317038 insp_id
978 site_id

Prepared By:

ALEXANDRA ANDRICOS, V.M.O USDA, APHIS, Animal Care

Title: VETERINARY MEDICAL OFFICER Inspector 5038

Date:

Apr-09-2007

Received By:

(b)(6), (b)(7)(c)

Title:

Date:

Apr-09-2007